## This Page Is Inserted by IFW Operations and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**


Defective images within this document are accurate representations of the original documents submitted by the applicant.


Defects in the images may include (but are not limited to):


- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS


## IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.











McCracken & Frank LLP (312) 263-4700 Applicants: Allen et al. - Docket:No.: J-3949 Title: "Housing and Actuating Apparatus and Methods Associated Therewith" Figs. 3 and 4 Sheet 3 of 11 90. FIG. 3 FIG. 4 .82 78°C 

Title: "Housing and Actuating Apparatus and Methods Associated Therewith"


Figs. 5A, 6 and 7

Sheet 5 of 11








F16. 7



Figs. 8 and 9 Sheet 6 of 11







McCracken & Frank LLP (312) 263-4700
Applicants: Allen et al.
- Docket:No.: J-3949 Title: "Housing and Actuating Apparatus and Methods Associated Therewith" Figs. 15, 16, 17, 18 and 19 Sheet 9 of 11 F16.15 F16,16 -15Z 204 10. 200 166 150 F16. F16.19 FIG. B 1\$2 208,90 200 < 200 -205 

Figs. 20, 21 and 22
Sheet 10 of 11




Fig. 23 Sheet 11 of 11